



Opel
Omega B
Model year: 1994 - 1997
Engine: all
With manual air-conditioning system

Humidity in the footwell

With the above-mentioned vehicles, humidity from the heating/evaporator housing can penetrate the interior footwell. This is because they do not have a water deflector. Vehicles produced after January 1996 already have a modified heating/evaporator housing with water deflector. In extremely problematic cases, the complete housing can be replaced by a modified one. Please contact an authorised dealer for this purpose.

Bulletin