



OPEL Vectra B, 1996 - 2002
OPEL Tigra, 1995 - 2000
OPEL Astra F, 1992 – 1998
OPEL Corsa B, 1993 – 2000
With engine code X16XEL

Engine occasionally fails
No ignition spark

Problem:

The engine can die now and then.
An event memory query shows that there is no entry in the event memory. It is possible that simultaneously there is no ignition spark on the spark plugs.

Cause:

Could be a earth connection between the ignition coil and the throttle valves housing.

Solution to the problem:

Check the cabling and screw fittings of the earth connection of the ignition coil and repair if necessary. Here it is recommended to replace the fastening screw with a tin-coated screw. (Opel catalogue no. 11 095 432)