



Opel Vectra C Model year: from 2002

Loss of refrigerant / Poor cooling performance of the air conditioning

If there are complaints with the above-mentioned vehicles about the cooling performance of the air conditioning or/and a loss of refrigerant is found, a leak in the expansion valve should be considered as a cause. If a loss of refrigerant is found, the expansion valve should be checked. To do this, it is necessary to remove the panelling of the water channelling. The leak is often caused by the O-rings of the connection elements to the expansion valve. New seal rings can be found in the *Behr Hella Service* range of spare and wearing parts.

Bulletin