



OPEL

Vivaro

Model year: starting 2007

Air conditioning unit with an evaporator

Loss of coolant

Damaged coolant hose

Problem:

A damaged coolant hose may lead to the loss of coolant. If coolant loss is observed on such a vehicle, special attention should be paid to the coolant hose between compressor and condenser. The hose can break due to vibrations caused by the condenser.

Possible cause:

Defective or non-existent tight attachment of the condenser. The auto manufacturer should in the meantime provide an additional bracket for the condenser.

Solution of the problem:

Replace the pipe and change the condenser (Code 60). Be sure that the condenser has an additional bracket. Alternatively, the condenser (Code CJ5) of the type "Air conditioning unit with additional rear end vaporizer" can be braced.