

08.11.2007

Peugeot 207 Model year: 04.2006 - 05.2007 Engine: 1.4i 16V (65 KW) Model year: 04.2006 - 01.2007 Engine: 1.6i 16V (80 KW)

Alternator failure / Battery discharged

With the above-mentioned vehicles, the alternator warning lamp can suddenly light up and the battery may have become discharged. A faulty alternator must be considered as the cause.

The vehicle manufacturer has informed all vehicle owners concerned and asked them to visit an authorised garage for the vehicles to be checked over. It must be assumed, however, that there are still vehicles on the road that were not checked or modified for various reasons.

Please bear this information in mind when you receive complaints related to a discharged battery or faulty alternator.





1-1