



Peugeot 306

Vehicle identification number: 30108962 - 30276791

Radiator fans do not switch off / battery run down

In the case of the above-mentioned vehicles with two-stage double fans the fans could keep running permanently after the ignition has been switched off. In many cases, the air conditioning and rear window heating remain switched on, too. This leads to the battery running down completely. The cause is often to be found in water in the electrical plug-type connections to the radiator fan. This water penetration can cause a short-circuit which leads to the radiator fan relay staying switched on although the ignition is switched off. This in turn can lead to the compressor or the rear window heating being switched on. During diagnosis of the electrical system (troubleshooting run-down battery, consumers switched on permanently), all electrical plug-type connections to the radiator fan should be checked for water penetration and/or corroded connectors.

It is also possible that vehicles outside the vehicle identification range specified above are affected.

Bulletin