



Peugeot 406

Model year: 1995–1999

Engine: All

With air conditioning

Radiator/Condenser fans fail

In the case of the above-mentioned vehicles, it may be that both radiator/condenser fans stop working. The fans are triggered via a separate radiator fan control unit. It receives its input signals both from the engine and the air conditioning control unit, and, as a result, triggers one or both fans via the radiator fan relays. If both fans stop working, the cause often lies with the radiator fan control unit. In relation to this, check for corrosion and contact faults in the wiring/connections. If necessary, the connections and the control unit, which is located in the mudguard area below the left-hand headlight, must be replaced.

In the course of model year 1999, the radiator fan control unit was integrated into the air conditioning control unit (vehicle interior).

Bulletin