



## **PEUGEOT**

### **807**

**Year of manufacture: 2002 - 2005**

#### **Condensation water outflow / Airbag monitoring light**

**Problem:**

Accumulation of water in the passenger footwell.  
The airbag monitoring lamp lights up. In an extreme case, the airbag(s) is/are activated.

**Possible causes:**

In case of accumulation of water in the footwell: Defective outflow of condensation water from the air conditioner.  
If the airbag monitoring lamp lights up: Water in the airbag control device.

**Remedy:**

Check and clean out the condensation water outflow; check the airbag control device for entry of water. Obtain further information on remedies from the auto manufacturer.

**Bulletin**