



Citroen C2, C3 Model year: from 03.2006

Dryer cartridge not replaceable

In the case of the above-mentioned vehicles, condensers with non-replaceable dryer cartridges have been fitted since March 2006.

Until this model year, it was possible in the case of the C3 to replace the cartridge integrated into the condenser. The new condenser, with the original-part no. 6455ET, no longer has a threaded cap for the dryer insert. Under part no. 8FC 351 300 371, *Behr Hella Service* offers for the C2 and the C3 a condenser with a threaded cap in the case of which the dryer insert can be changed.



Bulletin