



Ford Galaxy ***Model years 2002 – 2006*** ***Engine: E5SB*** ***All models***

Airbag SRS – Hazard warning lamp lights up Malfunction of brake light switch

If the SRS hazard warning lamp (see figure) lights up during driving in the above vehicles, one possible cause may be a wrong adjustment of the brake pedal switch.

In this case, the basic setting of the switches should be checked and adjusted if necessary.

Please note, in this context, the installation instructions and safety regulations for air bag systems of the vehicle manufacturer.

