



Lancia Ypsilon **All models with air conditioning** **system and 4-fold refrigerant pressure** **switch**

Refrigerant temperature display **sometimes too high, radiator fan only** **runs at full speed.**

If there are complaints with these vehicles that the refrigerant temperature display briefly (approx. 10 seconds) shows a value that is too high and the radiator fan only runs at full speed, one possible cause is a faulty radiator fan resistor. The radiator fan resistor has to be replaced for the fault to be eliminated.

Note:

The 4-fold refrigerant pressure switch can be recognised by the 5-pole connection plug.