## Bulletin



© Hella KGaA Hueck & Co., Lippstadt

14 December 2006

----

## Renault Laguna All models with 1.9 DCI engine From model year 2002

## The starter turns but the engine will not start.

If there are complaints with these vehicles that the starter turns but the engine will not start, one possible cause is the engine control unit. Due to blocked water drains, water accumulates in the area below the cowl panel, behind the splash wall, and penetrates the engine control unit. The moisture ingress causes the engine control unit, and therefore the entire engine electronics, to fail. In order to eliminate the fault, the water drains must be cleaned, so that the accumulated water can drain. If the problem is detected early, it may be sufficient to dry the engine control unit in order to restore operation. In extreme cases, it may be that the engine control unit has to be replaced.



