



## **Opel Agila Corsa C Model year 2004-2005 With engine Z10XEP, Z12XEP, Z14XEP**

### **Engine judders, fault code in fault memory.**

If there are complaints with these vehicles that the engine judders and that fault code P1405 is stored in the fault memory of the engine control unit, one possible cause may be the exhaust-gas-recirculation valve. In this case, the EGR valve is blocked by particles from the catalyst. In order to eliminate the fault, a servo-component test should be carried out using suitable diagnosis equipment, so that the deposited particles are freed. After this, allow the engine to run at a high speed for a short period. Following this, the fault memory must be deleted.

**Bulletin**

